*RETURN TO FMF - LOCATION 7540 PEC-EDIT

QUERY CONTROL FORM			RTIS USE ONLY
Application No. 09836,779 Prepared by AMW			Tracking Number
Examiner-GAU E. H.	. LEE Date	3-29-04	Week Date
- /	732 No. of queri	es /	
CB			
JACKET			
a. Serial No.	f. Foreign Priority	k. Print Claim(s)	p. PTO-1449
b. Applicant(s)	g. Disclaimer	I. Print Fig.	q. PTOL-85b
c. Continuing Data	h. Microfiche Appendix	m. Searched Column. PTO-270/328	s. Sheets/Figs
d. PCT	i. Title	o. PTO-892	t. Other
e. Domestic Priority	j. Claims Allowed	0.110-032	d. Gallor
SPECIFICATION	MESSAGE /MPROP	OR DEPENDE	ENCY: Original
a. Page Missing			
b. Text Continuity	claims 11, 12 an	1 13 Car	ch depends upon
c. Holes through Data			
d. Other Missing Text	itself. Please	e correct.	Thank Gov.
e. Illegible Text			
f. Duplicate Text			
g. Brief Description			
h. Sequence Listing			
i. Appendix			
j. Amendments			
k. Other			
CLAIMS			
a. Claim(s) Missing			
b. Improper Dependency			
c. Duplicate Numbers			
d. Incorrect Numbering			initials AMW
e. Index Disagrees	RESPONSE		
f. Punctuation			
g. Amendments	PLEASE	MAKE	THE FOLLOWING
h. Bracketing	CIE	MAKE ANGES.	•
i. Missing Text			
j. Duplicate Text			
k. Other			

initials



and wherein either the holes are not all identical in shape and size, the protrusions are not all identical in shape and size, or both.

10. A method of producing a brush, comprising:

forming a bristle carrier including at least one hole having a protrusion projecting from a bottom of the hole;

heating the protrusion and at least a portion of the wall of the hole; and inserting a sheaf of bristles into the hole, wherein

when heated, material from the protrusion flows about the

bristles, retaining them in the hole, and

the sheaf of bristles is not perpendicular to a surface of the bristle carrier containing an opening of the hole.

10

11. The method of claim \mathcal{V} , further comprising fusing an end of the sheaf to form a fuse-ball having a greater diameter than a diameter of the sheaf.

11

12. The method of claim 1/2, wherein the fusing is performed thermally or chemically.

Į1

- The method of claim 13, wherein the fusing is performed thermally, and wherein the sheaf is inserted in the hole while the fuse-ball is still warm.
 - 14. The method of claim 12, further comprising pressing a portion of the wall of the hole around the fuse.

25

15

5

15. The method of claim 11, wherein the step of forming comprises injection molding or compression molding.

Add AZ